



FACILITY EVALUATION REPORT

Fire Station 2

14396 HWY-17, Dryden, ON

Facility Details

Gross Area (Sq.m.):	593		
Construction Year:	1991		
Replacement Cost:	\$ 1.8 million		
Previous Evaluation:	nil.	By:	nil.
Date of Evaluation:	09-Aug-22	Project #:	22091
Evaluator:	Quartek Group Inc. architects, engineers, planners		

Repair/Maintenance Events **See attached breakdown of action items by period.*

0-5 year Recommended Event Action Budget	\$	453,050.00
6-10 year Recommended Event Action Budget	\$	102,663.00
11-20 year Recommended Event Action Budget	\$	184,168.00

General Summary:

The facility appears to be purpose-built using wood framing and metal siding clad on its walls and on its roof. With the residential level of finishes otherwise observed, the building would not be in a premium category of durability and due to its age, it would not be deemed energy efficient. The second floor is not barrier-free accessible. There are several repair/replacement events noted in the survey, particularly in connection with the site parking lot and laneways. As well there are mechanical and electrical replacement items listed for attention within the next 5 years.

Structural Summary (Superstructure):

The foundations appears to be strip footings with a slab-on-grade floor throughout. The identified structural events were minimal and pertaining to a trench drain repair replacement.

Envelope Summary (Shell):

The envelope would provide a generally low insulation values compared to a new facility. There has been a water leakage causing localized damage; Please review the Pinchin report dated 2022, that describes remediation measures undertaken. Other elements of the envelope are original and will warrant replacement particularly windows. A study to evaluate the scheduled replacement and budgeting is recommended.

Interior Summary:

The interior is generally in good to fair condition. There are surfaces that are showing age. We have listed wall repainting and replacement of ceiling tiles after minor remediation work is undertaken.

Mechanical Summary:

While the facility is reported to have good operational history, there are a number of primary mechanical equipment items noted to be into the normal replacement range when they are likely to fail or lose partial function at some point within the next ten years. Similar comment applies to some fixtures noted. Due to the overall age of system installation, the theoretical life of various mechanical systems (piping, drains, ducting, etc.) are likely to require partial or whole replacement within the event horizon of the study.

Electrical Summary:

Due to the concealment of most electrical wiring, the study could not fully determine the wiring age or its overall condition beyond a sampling of the age of various panel boards, some of which are due for replacement within the next 5 to 10 years. The emergency lighting batteries will require routine replacement. Due to the overall age of system installation, the theoretical life of various electrical systems are likely to require partial or whole replacement.

Study References and Methodology:

The study provides a snapshot of the physical condition and age of building components or systems of the facility at the time of the site visit conducted for evaluation. The site visit is a brief visual, non-invasion walk-through survey of the readily accessible aspects of the building and its site. The survey should not be considered technically exhaustive. The study team also reviews any technical drawings and or other reports and/or building records that are supplied to the evaluator by the facility owner/operator. A brief interview is conducted with maintenance personnel or building users, when possible, to further ascertain known issues for the facility assessment.

The study follows the Uniformat II method for categorizing building components and identifies a potential repair or replacement event. Such an event is provided with an approximate estimate of quantities and cost to maintain the building and not necessarily create an improvement of building feature or performance. The events are organized into potential risk of occurrence over three periods starting with the next five years, years 6 to 10 thereafter and for a period not exceeding a horizon of 20 years from the visit date. In each period, the variables affecting repair or replacement events diminish in accuracy of event cost the further this action is undertaken from the date of the report.

The methodology used in this study is based on the contract scope and the terminology/limitations of ASTM E2018-15 Standard Guide for Property Assessments. Event estimates provided herein are represented in 2022 Canadian dollars. Future periods referred to in this report should be indexed based on several factors affecting future costs, of which may include inflation indexing, regional changes in labour or material availability in the construction industry. The reader would apply these accordingly.

Extra Study: In context to a Unifomat II item, our report may on occasion make a recommendation for the City to engage an expert to conduct addition investigation and/or study concerning an existing building component. This is because a determination could not be reasonably ascertained by Quartek within the parameters of our study scope or because the study/investigation will afford the City more latitude as to the best remedial action other than simply a repair/replacement option. The study/investigation recommendation is in itself an event and we identify a potential cost amounts for budgeting this action. The studies we noted:

Window (and door) Condition Study: This is a situation we find commonly with window frames and glazing conditions. Glazing may have been replaced or glazing replacement may be one of the options for the City to consider instead of whole window (frame) replacement often at considerably less cost and with improved performance. Where we have recommended a study, this precedes any budgeting exercise. So in the case where we proposed

We may determine that as a follow-up after implementing a recommended study/investigation, the result (findings) are likely to facilitate a cost for replacement, remediation or other action, a budgetary amount in the form of an allowance has been noted. The findings of the recommended study may exceed this allowance depending on the outcome, but some funding will presumably be allocated to cover a portion of the action.

Theoretical Life: (References provided from RE Capp and Other M/E reference documents) We have provided selective examples of typical operational/functional life for various building components as a general guide to readers:

Electrical Components

Electrical Switch gear	40 years
Electrical Light Fixtures	20 - 30 years + *Efficiency Obsolescence
Radiant Electrical Heating	20 years + *Efficiency Obsolescence
Main Conductors	60 – 70 years
Transformers	30 - 40 years + *Efficiency Obsolescence

Mechanical Components

Plumbing Piping (Copper)	50 - 60 years
Hydronic Piping (galv.Iron)	70 - 90 years + *Efficiency Obsolescence
Washroom Fixtures	30 years + *Efficiency Obsolescence
San.Waste Piping (Iron)	60 – 70 years
Gas Furnaces(combustion)	20 - 30 years + *Efficiency Obsolescence
Air handling with H/C coils	50 years + *Efficiency Obsolescence
Light Metal Ducting	60 – 70 years

Enclosure Components

Window Units (Alum.Frame)	40 - 50 years + *Efficiency Obsolescence
Flat Roofing Membranes	30 - 40 years + *Efficiency Obsolescence
Sloped Roofs (Shingles)	20 - 40 years
San. Waste piping (Iron)	30 – 70 years
Standard Brick (Veneer)	80 - 100 years
Conventional EIFS wall	40 - 60 years
Exterior Metal Siding	40 - 60 years

Superstructure Components

Concrete Foundations	40 - 50 years + *Efficiency Obsolescence
Structural Steel Framing	30 - 40 years + *Efficiency Obsolescence
Masonry Walls	20-40 years
San. Waste piping (Iron)	30–70 years

Copyright

Copyright 2024, Corporation of the City of Dryden, Ontario. All Rights Reserved. The preparation of this project was carried out with assistance from the Government of Canada and the Federation of Canadian Municipalities. Notwithstanding this support, the views expressed are the personal views of the authors, and the Federation of Canadian Municipalities and the Government of Canada accept no responsibility for them

General Report Disclaimer:

The report should be reviewed in context to any prior hazardous building materials assessment studies as to further budgeting considerations beyond the limited repair/replacement events described in this report. The intended use of the report is for assistance with long-range asset management planning for a facility under its current state so ideally adequate budgeting can be provided.

The repair replacement events identified in the report are not intended to capture routine maintenance of various components of the facility that would be generally anticipated as part of the day-to-day operations. Deferred maintenance can lead to earlier than predicted failure of equipment, systems, materials, etc. Notwithstanding the described methodology, the study findings are only as accurate as the available information provided, the allowable time to conduct a site visit to properly document findings and the level of access afforded the surveyors by the owner's representative. Costing accuracy may vary due to our ability to fully assess that collateral affects of a repair/replacement event on other elements of the building or surrounding site.

Part A Substructure**A10 Foundations**

A010	Slab On Grade					
	A101004	Trenches				
		Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location
						Flag
						Trenches in garage bays.
		Allowance		1	\$ 25,000	Study Rq'd.
		Condition	Trench in east garage bays reported to be in poor condition. Does not drain well. Allowance given for trench and pipe replacement.			
		Scope	Cast-in-place trenches. Assemblies include excavation, hand shaped bottoms, compacted backfill, formwork, reinforcing steel, concrete, and concrete finish. Examples include trench drains and dust trenches.			

Part B Shell**B20 Exterior Enclosure**

B2010	Exterior Walls					
	B201008	Exterior Soffits				
		Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location
						Flag
		LM		4	\$ 2,000	Prefin. metal soffit above door on Northwest bldg corner.
						Replace
		Condition	Soffit is damaged.			
		Scope	Assemblies would include all associated materials which make up the soffit and supports for the soffit. Typical materials would include wood, aluminum, exterior grade gypboard, stucco, etc.			
B2020	Exterior Windows					
	B202001	Windows				
		Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location
						Flag
			Study	1	\$ 3,000	All windows on main and upper floor.
						Study Rq'd.
		Condition	Wood frames and sashes appear to be original to the building and warrants a review of the seals, performance of and operation.			
		Scope	Fixed or operable windows located in exterior walls or exterior skin. Assemblies would include frames, glazing, caulking, finishes, and other associated work.			

B2030

Exterior Doors

B203001 Solid Doors

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		2	\$ 1,200	Exterior HM access Doors facing south and east. Double door and single door.	Coating

Condition exterior painted finish is faded : to be cleaned of rust, prime coated and finish paint applied.

Scope Assemblies include all exterior solid doors, hollow metal or wood with frames. Solid doors may include viewing lites in door. Door hardware is located in B203008 EXTERIOR DOOR HARDWARE.

Part C Interiors**C30 Interior Finishes**

C3030

Ceiling Finishes

C303003 Gypsum Wallboard Ceiling Finishes

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		108	\$ 16,400	Apparatus Area; See PINCHIIN report for localized ceiling remediation.	Repair

Condition Significant number of openings in fire protection , exposing existing wood joists and some locations around duct chases.

Scope Assemblies include gypsum wallboard applied to interior ceilings. Furring strips or channels are included in this assembly if they are applied directly to the ceiling surface. If the gypsum board is applied to a suspended ceiling system, the suspended system would be in Assembly Category C303007. This assembly does not include items that directly apply to ceiling finishes covered elsewhere in this subsystem.

C303004 Acoustical Ceiling Tile and Panels

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		175	\$ 8,180	In former municipal offices and meeting room on ground floor; See PINCHIIN report for localized ceiling remediation.	Replace

Condition Significant number of openings in fire protection , exposing existing wood joists and some locations around duct chases.

Scope Assemblies include acoustical ceiling tiles and panels. The suspension system, if required, is in Assembly Category C303007. This assembly does not include items that directly apply to ceiling finishes covered elsewhere in this subsystem.

Part D Services**D20 Plumbing**

D2010

Plumbing Fixtures

D201001 Water Closets

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		2	\$ 4,760	main floor washrooms	Replace

Condition Older High-volume fixtures. At theoretic life.

Scope Self explained

D201002 Urinals

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		2	\$ 8,400	main floor washrooms	Replace

Condition Older High-volume fixtures. At theoretic life.

Scope Self explained

D201003 Lavatories

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		3	\$ 5,460	In washrooms	Replace

Condition Older fixtures and faucets. At theoretic life.

Scope Self explained

D201004 Sinks

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		2	\$ 3,360	In washrooms	Replace

Condition Older fixtures and faucets. At theoretic life.

Scope Self explained

C2020

Domestic Water Distribution

D202001 Pipes and Fittings

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 8,750		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope Assemblies include all pipe, fittings, and associated work with regard to domestic water supply. The unit of measure at the assembly level is number of fixtures.

D202002 Valves and Hydrants

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 700		Replace
Condition	Exceeds theoretic life of Equipment Operation. Not efficient				
Scope	Assemblies include all valves and hydrants. Hose bibbs are included in this assembly. The unit of measure at the assembly level is number of valves and hydrants.				

D202003 Domestic Water Equipment

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		1	\$ 2,100		Replace
Condition	Exceeds theoretic life of Equipment Operation. Not efficient				
Scope	This assembly includes equipment associated with the domestic water supply, including fittings, and specialties required for hookup. Assemblies include hot water heaters, water treatment plant, i.e., water softeners, filters, distillers, etc.; pumps directly associated with domestic water supply; and tanks for the potable hot or cold water system. The unit of measure at the assembly level is pieces of equipment.				

D202004 Insulation and Identification

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 3,500		Replace
Condition	Exceeds theoretic life of Equipment Operation. Not efficient				
Scope	Assemblies include insulation used in association with domestic water supply. The unit of measure at the assembly level is number of fixtures.				

D202099 Other Domestic Water Supply

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 11,200		Replace
Condition	Exceeds theoretic life of Equipment Operation. Not efficient				
Scope	Domestic water supply not described by the assembly categories listed above.				

D30 HVAC

D3020

Heat Generating Systems

D302003 Furnaces

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
KW	EA	1	\$ 18,200		Replace

Condition Exceeds theoretical life of equipment operation. Not efficient

Scope This is a system that heats air. Assemblies would include furnace and necessary fittings and specialties required for hookup, including flue and stack. The unit of measure at the assembly level is each.

D302004 Fuel-Fired Unit Heaters

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
KW	EA	1	\$ 7,000		Replace

Condition Exceeds theoretical life of equipment operation. Not efficient

Scope Assemblies would include unit heaters and the energy supply system hookup (other than electrical), including all necessary pipe, fittings, and specialties required for hook-up. Flue and stack, if required, are included in this assembly. The unit of measure at the assembly level is each.

D3030

Cooling Generating Systems

D303002 Direct Expansion Systems

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
KW	EA	1	\$ 7,000		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope Assemblies include condensers, compressors, heat pumps, and refrigerant piping. The unit of measure at the assembly level is each.

D3040

Distribution Systems

D304007 Exhaust Systems

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
L/S	Assembly	1	\$ 840		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope Assemblies include ductwork grilles, registers, diffusers, fans, and all associated work. The unit of measure at the assembly level is each system.

D50 Electrical**D5010 Electrical Service and Distribution****D501005 Panels**

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Panel 3 in garage	

AMP		1	\$ 2,800		Replace
-----	--	---	----------	--	---------

Condition	Replace Federal Pioneer Stablock Panel board. Panel at or near end of theoretical life.				
-----------	---	--	--	--	--

Scope	Branch circuit panel boards. Assemblies include panel boards, breakers, conduit, and wire.				
-------	--	--	--	--	--

Part E Equipmt. & Furnishings

No Events

Part F Special Construction

No Events

Part G Bldg. Siteworks**G20 Site Improvements****G2020 Parking Lots****G202001 Bases and Sub-bases**

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Asphalt base and granular sub-base.	

EA		1025	\$ 32,200		Replace
----	--	------	-----------	--	---------

Condition	Appeared to be in poor condition. Unevenness noted throughout.				
-----------	--	--	--	--	--

Scope	These are the compacted and prepared gravel or soil layers that are placed prior to the installation of the final surface. The subbase is placed and compacted before the base layer is applied.				
-------	--	--	--	--	--

G202001 Bases and Sub-bases

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Concrete apron in front of garage doors	

EA		250	\$ 7,900		Replace
----	--	-----	----------	--	---------

Condition	Appeared to be in poor condition. Unevenness noted throughout.				
-----------	--	--	--	--	--

Scope	These are the compacted and prepared gravel or soil layers that are placed prior to the installation of the final surface. The subbase is placed and compacted before the base layer is applied.				
-------	--	--	--	--	--

G202003 Paved Surfaces

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Asphalt parking lot.	
EA		1025	\$ 149,000		Replace

Condition Appeared to be in poor condition. Cracking and unevenness noted throughout.

Scope This is material that is placed atop the base layer to provide the driving surface.

G202003 Paved Surfaces

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Concrete apron in front of garage doors	
EA		250	\$ 42,300		Replace

Condition Appeared to be in poor condition. Cracking and unevenness noted throughout.

Scope This is material that is placed atop the base layer to provide the driving surface.

G202004 Marking and Signage

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Concrete apron in front of garage doors	
EA		1	\$ 700		Replace

Condition To be repainted at same time as repaving event.

Scope This includes painting of the parking stalls, signage, etc.

G202005 Guardrails and Barriers

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Bollards at Garage doors	
EA		6	\$ 8,700		Replace

Condition Appeared to be in fair condition. A few bollards appeared to have been impacted.

Scope Guardrails, barriers, parking stops and other similar devices.

G202006 Resurfacing

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Gravel parking lot	
EA		1400	\$ 50,000		Replace

Condition Appeared to be in fair condition. Surface appeared uneven and granular compacted. Regrading and resurfacing recommended.

Scope This is the placement of an asphalt wearing course over the existing parking surface.

G40 Site Electrical Utilities PreparationsG4020 **Site Lighting**

G402006 Exterior Lighting Fixtures and Controls

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Pole mounted lights on perimeter of paved parking lot. Wall mounted light fixtures on building.	
EA			\$ 22,400		Replace

Condition Light fixtures and poles appear to be original and near end of theoretical life.

Scope Includes fixtures, controls, and all components used in conjunction with

Part A Substructure

No Events

Part B Shell**B20 Exterior Enclosure****B2010 Exterior Walls****B201011 Joint Sealant**

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
LM		300	\$ 2,000	General maintenance labour and sealant supply to various joint locations throughout.	Repair
Condition Some caulking has dried and is cracked; other evidence of gaps and lack of elasticity. Theoretical life of exterior sealant is 10 to 15 years.					
Scope Exterior application of joint sealants					

B30 Roofing**B3010 Roof Coverings****B301005 Gutter and Downspouts**

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
LM		112	\$ 1,200	Replaced damages down spouts	Replace
Condition Denting and some have split seams					
Scope Assemblies include all gutters, downspouts, and associated work including splash blocks.					

Part C Interiors**C10 Interior Construction****C1010 Partitions****C101008 Joint Sealant**

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
LM			\$ 1,600	General Locations Throughout.	Maint'nc.
Condition General locations at joints, dissimilar materials and wall penetrations.					
Scope Assembly includes caulking, gasketing between dissimilar materials and at joints.					

C30 Interior Finishes

C3010

Wall Finishes

C103005 Painting to Walls

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		1021	\$ 22,447	all drywall surfaces on main and second floor	Coating

Condition General paint wear and damage over period of use.

Scope This assembly includes painting, spackling and sealant applied directly to an interior wall surface.

C30 Interior Finishes

C3020

Floor Finishes

C302005 Carpeting

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		201	\$ 13,140	Misc. locations in former municipal offices, and in upper floor office and exercise room.	Replace

Condition Carpet in fair condition: signs of wearing /stained in places.

Scope Sheet or tile carpet with appropriate underlay

D20 Plumbing

D2010

Plumbing Fixtures

C2030

Sanitary Waste

D203001 Waste Pipe and Fittings

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 5,250		Replace

Condition Exceeds theoretic life of System Operation.

Scope Assemblies include all pipe, fittings, and associated work with regard to sanitary waste pipe and fittings. The unit of measure at the assembly level is number of fixtures.

D203002 Vent Pipe and Fittings

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA	Assembly	1	\$ 1,750		Replace

Condition Exceeds theoretic life of System Operation.

Scope Assemblies include all pipe, fittings, and associated work with regard to sanitary vent pipe and fittings. The unit of measure at the assembly level is number of fixtures.

D203003 Floor Drains

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		2	\$ 7,776		Replace

Condition Exceeds theoretic life of System Operation.

Scope Assemblies include all floor drains. Hub drains are considered to be pipe and are not included in this category. The unit of measure at the assembly level is number of drains.

D30 HVACD3010 **Energy Supply**

D301002 Gas Supply System

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
KW	Assembly	1	\$ 8,300		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope This category includes both natural gas and LPG. Assemblies include metering and regulation equipment, storage equipment, transfer equipment, and distribution piping. The unit of measure at the assembly level is each system.

D3050 **Terminal and Package Units**

D305006 Packaged Units

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		1	\$ 5,600		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope Assemblies include complete package units, with integral roof top curbs and all associated devices. A heating system can be selected from hot water, steam coil, or gas furnace and can be a single or multi-zone system. The unit of measure at the assembly level is each.

D50 ElectricalD5020 **Lighting and Branch Wiring**

D502002 Lighting Equipment

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 14,000	Newer LED light fixtures installed in garage. Older fluorescent light fixture installed through remainder of building	Replace

Condition Replace ballasts and lamps in fluorescent light fixtures. Replace drivers in LED light fixtures.

Scope This assembly includes fixtures, conduit, wire, and switching devices.

D5030

Communications and Security

D503001 Fire Alarm Systems

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 17,500	Fire Alarm Control Panel and annunciator at main entrance. Detectors, pull stations and bells located throughout building.	Replace
Condition Replace Fire Alarm Panel and devices at end of theoretical life.					
Scope Assemblies include wire, conduit, conduit support or fastening systems, fire alarm devices, fire detection devices, safety switches, all electrical connections, and other associated items					

D5090

Other Electrical Services

D509002 Emergency Lighting and Power

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 2,100	Multiple battery units and remote heads located throughout building	Replace
Condition Exceeded reliable Operation Life: Replace batteries at end of life. Replace lamps in remote heads.					
Scope Assemblies include fixtures, motors used for power generation, connection and testing, transfer switches, conduit, wire, battery chargers, batteries, and solar panels.					

Part E Equip. & Furnishings

No Events

Part F Special Construction

No Events

Part G Bldg. Siteworks

No Events

Part A Substructure

No Events

Part B Shell**B20 Exterior Enclosure**

B2010

Exterior Walls

B201010 Exterior Coatings

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		421	\$ 20,840	Metal siding walls	Coating

Condition Typical deterioration of prefinished painted siding surface from exposure to elements, discolouration.

Scope Assemblies include paint, stucco, etc. The unit of measure at the assembly level is area of exterior coatings.

B2020

Exterior Windows

B202004 Exterior Glazing

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM	Allowance	8	\$ 24,000	All exterior Glass to be reviewed for gasketing, glazing and performance.	Allowance

Condition Periodic scheduled review of glazing performance, sealed unit performance, etc.

Scope In addition to glass, this includes acrylic, polycarbonate, and plastic glazing.

B30 Roofing

B3010

Roof Coverings

B301001 High Slope Roof Coverings

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		approx. 495	\$ 51,728	Pre-finished metal roof system	Replace

Condition Original factory-applied coating is etched and discoloured and is fair condition; The metal roof can be replaced or the roof can receive a purpose-specific roof coating to extend the life of the roofing.

Scope Assemblies include roof coverings, such as shingle, wood shake, and standing seam, etc.

Part C Interiors

No Events

Part D Services**D30 HVAC**

D3040

Distribution Systems

D304001 Air Distribution, Heating and Cooling

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
L/S	Assembly	1	\$ 28,000		Replace

Condition Exceeds theoretic life of Equipment Operation. Not efficient

Scope Assemblies include heating coils, cooling coils, and fittings and specialties required for water hook-up. This assembly also includes duct heaters, filters, humidifiers, supply and return ductwork, dampers, fire dampers, supply and return grilles, registers and diffusers, turning vanes, sound traps, and all associated insulation. The unit of measure at the assembly level is CF/M.

D50 Electrical

D5010

Electrical Service and Distribution

D501005 Panels

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
				Panel MO and Panel FH	
AMP		1	\$ 5,600		Replace

Condition Replace panelboards at end of theoretical life.

Scope Branch circuit panel boards. Assemblies include panel boards, breakers, conduit, and wire.

D5020

Lighting and Branch Wiring

D502002 Lighting Equipment

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 14,000	Newer LED light fixtures installed in garage. Older flourescnet light fixture installed through remainder of building	Replace

Condition Energy Reduction Payback: Replace ballasts and lamps in fluorescent light fixtures. Replace drivers in LED light fixtures.

Scope This assembly includes fixtures, conduit, wire, and switching devices.

D5090

Other Electrical Services

D509002 Emergency Lighting and Power

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 2,100	Multiple battery units and remote heads located throughout building	Replace

Condition Exceeded reliable Operation Life: Replace batteries at end of life. Replace lamps in remote heads.

Scope Assemblies include fixtures, motors used for power generation, connection and testing, transfer switches, conduit, wire, battery chargers, batteries, and solar panels.

D509005 Electrical Heating

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM			\$ 8,400	Electric baseboard heaters in ground floor and second floor office areas. Unit heaters in garage. Fan forced heater in ground floor office area and second floor washroom.	Replace

Condition Exceeded reliable Operation Life and New, more efficient products for replacement.

Scope Items could include baseboard heaters and wall and ceiling heaters. Assemblies include safety switches, control devices, heaters, conduit, and wire.

Part G Bldg. Sitewoks**G20 Site Improvements**

G2020

Parking Lots

G202006 Resurfacing

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
SM		1025	\$ 27,400	Asphalt parking lot resurfacing.	Replace

Condition Patched multiple times and appears to be settled in areas. Block cracking was observed throughout the parking lot. It is expected that resurfacing will address this issue.

Scope This is the placement of an asphalt wearing course over the existing parking surface.

G40 Site Electrical Utilities Preparations

G4020

Site Lighting

G402006 Exterior Lighting Fixtures and Controls

Unit/Meas.	O/Factor	Quantity	Event \$ Est.	Location	Flag
EA		150	\$ 2,100	Wall and or ceiling mounted light fixtures at building entrance / exits. Façade flood lighting near main entrance.	Replace

Condition Depression: Regrading required to address drainage issues. Possible underdrainage required

Scope Includes fixtures, controls, and all components used in conjunction with

Exterior and Interior Views



Site and M/E Images

