



Duke Street Bridge over CP Railway

For The

City of Dryden



Ref. No. JML2024090

December 2024

DUKE STREET BRIDGE OVER CP RAILWAY

1.0 Description

The Duke Street Bridge over CP Railway is located approximately 200 metres south of the Duke Street/Hwy 17 intersection. The structure is currently not load posted.

The structure is a double lane, three span bridge consisting of steel girders and a concrete deck supported on concrete piers and concrete abutments. The overall length of the bridge is approximately 35.5 meters, and the overall width of the bridge is 12.4 meters. The span lengths are 11.4 m, 11.5 m, and 11.4 m from south to north.

The deck consists of an asphalt wearing surface on a 178 mm thick reinforced concrete deck. A railing system exists at both sides of the bridge which consists of four horizontal HSS rails at the west side and two horizontal HSS rails at the east side with a steel flex beam guide rail at the approaches. A concrete sidewalk is located along the west side of the bridge, and a concrete curb is located along the east side of the bridge. Concrete parapet walls are located at the four corners of the bridge.

The deck is supported by five W610 ACR steel girders. The superstructure also includes ACR steel end and intermediate diaphragms. The ends of each steel girder sit upon elastomeric bearing pads at the piers and abutments. The abutments, wingwalls, and piers consist of reinforced, cast-in-place concrete.

2.0 Significant Findings

One full width medium crack and two full width narrow cracks were observed at the sidewalk.

Gravel has accumulated on top of the curb at the bridge and the approaches.

Delamination was observed at all four parapet walls. Light pattern cracking was observed at the inside faces of all parapet walls. The expansion joints have shrunk and are beginning to fail.

Gravel has accumulated on the base plates at the east and west side railing system posts.

A wide, full roadway width asphalt crack exists at both approach slab joints.

Light pattern cracking was observed throughout the northwest wingwall.

The steel beam guide rail is off clip angle shelves at end posts at northeast corner of site.

Erosion has occurred at top of embankment at southwest corner of bridge, and southeast end of

site.

Wire rope cables are loose at the approach railing system.

Rotated offset timbers were observed at southwest corner of site.

Gravel has built-up in front of steel beam guide rail at south approach to bridge.

Two full height medium cracks were observed at the north and south abutments.

Three areas of delamination were observed at the north abutment. Delamination and two spalls were observed at the south abutment.

Medium pattern cracks were observed at the sides of the abutments.

Delamination and one wide crack was observed at the south pier. A spall with exposed rebar, one area of delamination, and one wide crack was observed at the north pier.

There are wide vertical gaps between the wingwalls and the sides of the abutments.

Graffiti was observed on the piers and abutments.

3.0 Conclusions and Recommendations

The BCI is the ratio of the value of each bridge element in its current state to the total replacement value of the bridge. The overall Bridge Condition Index (BCI) of Duke Street Bridge over CP Railway is 77. The BCI value of the bridge indicates the bridge is in good condition.

We recommend the following remedial repairs be done within the next 1-5 years:

- Seal the cracks at the sidewalk with polyurethane.
- Remove the gravel from the curb and the base plates at the east and west side railing system posts.
- Reface the parapet walls. Provide new expansion joints.
- Rout and seal asphalt cracks at the approaches.
- Modify guide rail to sit upon shelf angles at termination posts.
- Restore eroded slopes at southwest corner of bridge and southeast end of site.
- Tighten all loose cables at the approach railing system.
- Remove/regrade gravel away from steel beam guide rail at south approach.
- Realign all rotated offset timbers behind steel beam guide rails.
- Remove graffiti off the piers and abutments.
- Inject the cracks at the abutments and piers with epoxy.
- Repair spalling and delaminated areas at the abutments and piers.

We recommend a monitoring system be established to measure and record the widths of the gaps between the wingwalls and abutments.

We recommend the next bridge inspection be done in 2026.

4.0 Estimated Construction Costs

The following are the estimated construction costs for the recommended remedial repairs:

Seal cracks at the sidewalk	\$ 1,000.00
Remove the gravel from the curbs	\$ 500.00
Reface parapet walls and provide new expansion joints.	\$ 15,000.00
Rout and seal asphalt cracks	\$ 1,000.00
Modify guide rail to sit on post shelves	\$ 1,500.00
Restore eroded embankments	\$ 500.00
Tighten loose cables	\$ 500.00
Remove/regrade gravel in front of guide rail	\$ 1,000.00
Realign plumb all offset timbers at posts	\$ 1,000.00
Inject cracks at abutments and piers	\$ 17,000.00
Repair spalling and delaminated areas at piers and abutments	\$ 21,000.00
Subtotal	\$ 60,000.00
Mob/Demob (20%)	\$ 12,000.00
Engineering/Contingency (35%)	\$ 21,000.00
Total Estimated Construction Cost	<u>\$ 93,000.00 + HST</u>

Even though the structural inspection was carefully done, we do not claim that the observations made represent all of the faults or imperfections which may exist.

Ontario Structure Inspection Manual – Inspection Form

MTO Site Number:

Inventory Data:			
Structure Name	Duke Street Bridge over CP Railway		
Main Hwy/Road #	594	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>	Crossing Type: <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input checked="" type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Hwy/Road Name	Highway 594/Duke Street		
Structure Location	300 m South of Duke Street/Hwy 17 Intersection		
Latitude	49°47' 45"N	Longitude	92°49' 20"W
Owner(s)	City of Dryden	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Region	Northwestern	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local <input type="checkbox"/>
MTO District	Thunder Bay	Posted Speed	50 No. of Lanes 2
Old County	Rainy River	AADT	% Trucks
Geographic Twp.	544	Inspection Route Sequence	
Structure Type	3 Span Bridge	Interchange Number	
Total Deck Length	35.5 (m)	Interchange Structure Number	
Overall Str. Width	12.4 (m)	Min. Vertical Clearance	(m)
Total Deck Area	440 (sq.m)	Special Routes:	<input type="checkbox"/> Transit <input type="checkbox"/> Truck <input checked="" type="checkbox"/> School <input type="checkbox"/> Bicycle
Roadway Width	9.1 (m)	Detour Length Around Bridge	3.5 (km)
Skew Angle	0 (Degrees)	Direction of Structure	North/South
No. of Spans	3	Fill on Structure	(m)
Span Lengths	11.4, 11.5, 11.4 (m)		

Historical Data:			
Year Built	1964	Year of Last Major Rehab.	2010
Last OSIM Inspection	2022	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	/ / (tonnes)
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey	2007		
Rehab History: (Date/description)			
2010 - Superstructure replaced and substructure repaired.			

Field Inspection Information:	
Date of Inspection:	October 8, 2024
Inspector:	Mohamed Chehabeddine, EIT, JML Engineering
Others in Party:	Lucas Sandberg, JML Engineering
Access Equipment Used:	
Weather:	Sunny
Temperature:	18° C

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey			
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Non-destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Detailed Timber Investigation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Post-Tensioned Strand Investigation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Underwater Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fatigue Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seismic Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Structure Evaluation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Monitoring			
Monitoring of Deformations, Settlements and Movements:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Monitoring Crack Widths:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Investigation Notes: Establish a monitoring system to measure the gaps between the wingwalls and abutments.			

Overall Structure Notes:	
Recommended Work on Structure:	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	Seal cracks at sidewalk with polyurethane. Remove gravel from top of curb and base plates. Reface concrete at parapet walls. Complete various repairs at approaches. Reface delaminated and spalling areas at piers and abutments and inject cracks with epoxy at piers and abutments.
Date of Next Inspection:	2026

Suspected Performance Deficiencies

- | | | |
|--|---|-------------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|---|--|---|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey Bridges - Maintenance | 16 Bridge Deck Drainage |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Decks			Length:	35.6 m	
Element Name:	Wearing Surface			Width:	9.1 m	
Location:				Height:	0.178 m	
Material:	Asphalt			Count:	1	
Element Type:				Total Quantity:	324 sq m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²)m / each / % / all		324			11
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Decks			Length:	35.6 m	
Element Name:	Deck Top			Width:	12.4 m	
Location:				Height:	0.178 m	
Material:	Cast-in-place concrete			Count:	1	
Element Type:				Total Quantity:	442 sq m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input checked="" type="checkbox"/>		
Protection System:	Waterproofing and asphalt					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²)m / each / % / all		442			
Comments:						
Unable to inspect deck top due to wearing surface.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Decks			Length:	35.6 m	
Element Name:	Soffit – Thin Slab			Width:	12.4 m	
Location:				Height:	0.178 m	
Material:	Cast-in-place concrete			Count:	1	
Element Type:				Total Quantity:	442 sq m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input checked="" type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²)m / each / % / all	195	247			
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Joints				Length:	9.1 m	
Element Name:	Expansion Joints				Width:		
Location:	North and South Approach				Height:		
Material:					Count:	2	
Element Type:					Total Quantity:	18 m	
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>		
Protection System:							Perform. Deficiencies
Condition Data:	Units m ² / (m) each / % / all	Exc.	Good 18	Fair	Poor		
Comments:							
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
						<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Element Group:	Sidewalks/Curbs				Length:	35.6 m	
Element Name:	Sidewalk				Width:	2.03 m	
Location:	West Side				Height:	0.2 m	
Material:	Cast-in-place concrete				Count:	1	
Element Type:					Total Quantity:	80 sq m	
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>		
Protection System:	None						Perform. Deficiencies
Condition Data:	Units m ² / (m) / each / % / all	Exc.	Good 79	Fair 1	Poor		
Comments:							
One full width medium crack. Two narrow cracks.							
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
						<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
Seal cracks with polyurethane.							

Element Group:	Sidewalks/Curbs				Length:	35.6 m	
Element Name:	Curbs				Width:	0.61 m	
Location:	East Side				Height:	0.2 m	
Material:	Cast-in-place concrete				Count:	1	
Element Type:					Total Quantity:	29 sq m	
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>		
Protection System:	None						Perform. Deficiencies
Condition Data:	Units m ² / (m) / each / % / all	Exc.	Good 28	Fair 1	Poor		
Comments:							
Gravel accumulation on top of curb. Light abrasion and impact damage at approaches.							
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
						02 <input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year Remove gravel.	

Element Group:	Barriers			Length:	3.9 m	
Element Name:	Parapet Walls			Width:	0.254 m	
Location:	North and South ends			Height:	1.12 m	
Material:	Cast-in-place concrete			Count:	4	
Element Type:				Total Quantity:	41 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:	Thoroseal					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	m ² (m) / each / % / all		20	15	6	
Comments:						
Scaling at northwest wall at south. Delamination at all walls. Light to medium pattern cracking throughout front faces. Wide crack at southeast wall where a future corner spall will occur. The expansion joints have cracked and are failing.						
Recommended Work:				Maintenance Needs:		
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Reface parapet walls. Replace expansion joints.						

Element Group:	Barriers			Length:	35.6 m	
Element Name:	Railing Systems			Width:		
Location:	West and East sides			Height:		
Material:	Steel			Count:	2	
Element Type:	HSS			Total Quantity:	71 m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	m ² (m) / each / % / all		71			
Comments:						
Excessive joints at east side. Rails touching at splice joint but separated greatly at opposite end at west side. Gravel accumulation on base plates at west side.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Remove gravel.						

Element Group:	Coatings			Length:	35.6 m	
Element Name:	Railing Systems			Width:		
Location:	West and East sides			Height:		
Material:	Hot Dip Galvanizing			Count:	2	
Element Type:				Total Quantity:	71 m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	m ² (m) / each / % / all		71			
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's				Length:	35.6 m
Element Name:	Girders				Width:	0.324 m
Location:	5 each span				Height:	0.611 m
Material:	Steel				Count:	5
Element Type:	I-Type				Total Quantity:	390 sq m
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input checked="" type="checkbox"/>	
Protection System:	ACR					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	<u>m²</u> / m / each / % / all	172	218			
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's				Length:	2.3 m
Element Name:	Diaphragms				Width:	0.086 m
Location:	Between Girders at Mid Span				Height:	0.381 m
Material:	Steel				Count:	26
Element Type:	Channel				Total Quantity:	26
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input checked="" type="checkbox"/>	
Protection System:	ACR					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	m ² / m / <u>each</u> / % / all		26			
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Abutments				Length:	
Element Name:	Abutment Walls				Width:	11.9 m
Location:	South Abutment				Height:	6.0 m
Material:	Cast-in-place concrete				Count:	1
Element Type:					Total Quantity:	72 sq m
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	<u>m²</u> / m / each / % / all		60	8	4	
Comments:						
Light to medium scaling at base of abutment. One delaminated area near top of abutment. Two spalls. Two full height medium cracks. Graffiti paint on abutment.						
Recommended Work:				Maintenance Needs:		
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year		
Repair delaminated and spalling areas. Inject cracks with epoxy.				Remove graffiti paint.		

Element Group:	Abutments				Length:	
Element Name:	Abutment Walls				Width:	11.9 m
Location:	North Abutment				Height:	6.0 m
Material:	Cast-in-place concrete				Count:	1
Element Type:					Total Quantity:	72 sq m
Environment:	Benign Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		55	12	5	
Comments: Two full height medium cracks, one full height wide crack. Three delaminated areas. Medium scaling at west and east corners, top, and edges. Graffiti paint on abutment.						
Recommended Work:				Maintenance Needs:		02
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year		
Repair delaminated areas. Inject cracks with epoxy.				Remove graffiti paint.		

Element Group:	Abutments				Length:	
Element Name:	Wingwalls				Width:	7.5 m
Location:	South Wingwall				Height:	4.8 m
Material:	Cast-in-place concrete				Count:	2
Element Type:					Total Quantity:	72 sq m
Environment:	Benign Moderate / Severe				Limited Inspection <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		68	2	2	
Comments: Large gap between wingwall and abutment wall. Light to medium pattern cracks at sides of abutments.						
Recommended Work:				Maintenance Needs:		18
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year		
Reface areas with pattern cracks.				Establish a monitoring system to measure gap width.		

Element Group:	Abutments				Length:	
Element Name:	Wingwalls				Width:	7.5 m
Location:	North Wingwall				Height:	4.8 m
Material:	Cast-in-place concrete				Count:	2
Element Type:					Total Quantity:	72 sq m
Environment:	Benign Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		67	3	2	
Comments: Large gap between wingwall and abutment wall. Light pattern cracking throughout. Scaling, medium cracks at sides at abutments.						
Recommended Work:				Maintenance Needs:		18
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year		
Reface deteriorated areas				Establish a monitoring system to measure gap widths.		

Element Group:	Abutments				Length:	
Element Name:	Bearings				Width:	
Location:	North and South Ends				Height:	
Material:					Count:	5 per end
Element Type:	Elastomeric pad				Total Quantity:	10
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / <u>each</u> / % / all	Exc.	Good 10	Fair	Poor	
Comments: Unable to inspect.						
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year

Element Group:	Piers				Length:	6.1 m
Element Name:	Piers				Width:	0.69 m
Location:	South Pier				Height:	7.7 m
Material:	Cast-in-place concrete				Count:	1
Element Type:	Tee Type Pier				Total Quantity:	120 sq m
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units <u>m²</u> / m / each / % / all	Exc.	Good 110	Fair 4	Poor 6	
Comments: Several patched areas. One delaminated area at north face. Delamination and wide crack at east underside. Graffiti paint on pier.						
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year
Repair delaminated areas. Inject cracks with epoxy.						Remove graffiti paint.

Element Group:	Piers				Length:	6.1 m
Element Name:	Piers				Width:	0.69 m
Location:	North Pier				Height:	7.7 m
Material:	Cast-in-place concrete				Count:	1
Element Type:	Tee type pier				Total Quantity:	120 sq m
Environment:	<u>Benign</u> / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units <u>m²</u> / m / each / % / all	Exc.	Good 109	Fair 4	Poor 7	
Comments: Several patched areas. Spall with exposed rebar at south face. Wide cracks at corner spall and delamination at east face. Graffiti paint on pier.						
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year
Repair delaminated and spalled areas. Inject cracks with epoxy.						Remove graffiti paint.

Element Group:	Piers				Length:	
Element Name:	Bearings				Width:	
Location:	North and South Pier				Height:	
Material:					Count:	10 per pier
Element Type:	Elastomeric pad				Total Quantity:	20
Environment:	Benign / Moderate / Severe				Limited Inspection <input checked="" type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m (each) / % / all	Exc.	Good 20	Fair	Poor	
Comments: Unable to inspect.						
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year

Element Group:	Foundations				Length:	
Element Name:	Foundation (below ground level)				Width:	
Location:	Piers and Abutments				Height:	
Material:					Count:	
Element Type:					Total Quantity:	
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each / % (all)	Exc. <input type="checkbox"/>	Good <input checked="" type="checkbox"/>	Fair <input type="checkbox"/>	Poor <input type="checkbox"/>	
Comments: Abutment and pier footings located below ground level. No signs of movement observed.						
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year

Element Group:	Embankments & Streams				Length:	
Element Name:	Slope Protection				Width:	
Location:	North and South ends				Height:	
Material:					Count:	
Element Type:					Total Quantity:	
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each (%) all	Exc.	Good 98	Fair	Poor	
Comments: Erosion occurring near southwest corner of bridge and southeast end of site.						
Recommended Work:				<input type="checkbox"/> Rehab <input type="checkbox"/> Replace		Maintenance Needs:
				<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year
						13 Top up gravel and apply seed and mulch to stabilize slope.

Element Group:	Approaches			Length:	6.1 m	
Element Name:	Wearing Surfaces			Width:	9.1 m	
Location:	North and South ends			Height:	0.075 m	
Material:	Asphalt			Count:	2	
Element Type:				Total Quantity:	111 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		107	2	2	
Comments: Wide, full roadway width transverse crack exists at both approaches.						
Recommended Work:				Maintenance Needs:		
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Rout and seal cracks.						

Element Group:	Approaches			Length:	6.1 m	
Element Name:	Approach Slabs			Width:	11.2 m	
Location:	North and South			Height:	0.254 m	
Material:	Cast-in-place concrete			Count:	2	
Element Type:				Total Quantity:	137 sq m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input checked="" type="checkbox"/>		
Protection System:	Waterproofing and asphalt					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		137			
Comments: Covered by asphalt.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Approaches			Length:	4 m	
Element Name:	Curb			Width:	0.413 m	
Location:	East curb			Height:	0.33 m	
Material:	Cast-in-place concrete			Count:	2	
Element Type:				Total Quantity:	4 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	(m ²) m / each / % / all		4			
Comments: Gravel accumulation on both curbs. Abrasion at northeast curb.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Remove gravel.						

Element Group:	Approaches				Length:	6.1 m
Element Name:	Sidewalk				Width:	1.5 m
Location:	North and South ends				Height:	
Material:	Cast-in-place concrete				Count:	2
Element Type:					Total Quantity:	18 sq m
Environment:	Benign / Moderate / <u>Severe</u>				Limited Inspection <input type="checkbox"/>	
Protection System:	Waterproofing and asphalt					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	<u>m²/m</u> / each / % / all		18			
Comments:						
Recommended Work:			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
					<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Element Group:	Approaches				Length:	
Element Name:	Railing				Width:	
Location:	North and South ends				Height:	
Material:	Steel Beam				Count:	
Element Type:					Total Quantity:	160 m
Environment:	Benign / <u>Moderate</u> / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor	
	<u>m²/m</u> / each / % / all		159	1		
Comments:						
Steel beam off clip angles at northeast corner of site. A few offset timbers have rotated. Impact damage at southeast corner.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years		Maintenance Needs:	
Modify steel beam to sit upon clip angles. Re-align offset timbers plumb.					<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	



Photo 1: North approach to bridge.



Photo 2: South approach to bridge.



Photo 3: East elevation looking west.



Photo 4: West elevation looking east.



Photo 5: Deck cross-section.



Photo 6: Underside of deck at south span.



Photo 7: Underside of deck at middle span.



Photo 8: Underside of deck at north span.



Photo 9: North abutment.



Photo 10: Northeast wingwall.



Photo 11: Northwest wingwall.



Photo 12: South abutment.



Photo 13: Southeast wingwall.



Photo 14: Southwest wingwall.



Photo 15: North face of north pier.



Photo 16: South face of north pier.



Photo 17: North face of south pier.



Photo 18: South face of south pier.




Photo 19: Looking east from bridge.




Photo 20: Looking west from bridge.



Photo 21: North approach slab joint.



Photo 22: South approach slab joint.



Photo 23: Northeast embankment.



Photo 24: Northwest embankment.



Photo 25: Southeast embankment.



Photo 26: Southwest embankment.



Photo 27: Barrier rail along east side of bridge.



Photo 28: Barrier rail along west side of bridge.



Photo 29: Abrasion damage along face and top edge of sidewalk.



Photo 30: Medium transverse crack in sidewalk.



Photo 31: Gravel accumulation on curb and post base plates.



Photo 32: Scaling, delamination and cracks at northeast parapet wall (typ.).



Photo 33: Wide gap at steel beam splice.



Photo 34: Wide gap between southeast wingwall and south abutment (typ.).



Photo 35: Vertical crack at north abutment.



Photo 36: Corner spalls at south pier.



Photo 37: Erosion at embankment northwest corner of bridge.



Photo 38: Erosion at embankment southeast area of site.



Photo 39: Steel beam guide rail off steel shelves at northeast end treatment.



Photo 40: Loose cables at south approach.



Photo 41: Gravel accumulation in front of guide rail at east side of south approach.



Photo 42: Rotated offset timber at southeast corner of site (typ.).