



Duke Street Bridge over Wabigoon River

**For The
City of Dryden**



Ref. No. JML2024090

December 2024

DUKE STREET BRIDGE OVER WABIGOON RIVER

1.0 Description

The Duke Street Bridge over Wabigoon River is located approximately 2 km west of the Duke Street/Hwy 17 intersection. The structure is currently not load posted.

The structure is a double lane, single span bridge consisting of steel girders and a concrete deck supported on concrete abutments. The overall length of the bridge is approximately 24.9 meters, and the overall width of the bridge is 11.0 meters.

The deck consists of an asphalt wearing surface on a 225 mm thick reinforced concrete deck. Concrete barriers exist along both sides of the bridge. The railing system consists of galvanized steel, 90 mm diameter HSS, and is located on top of the concrete barriers. A steel flex beam guide rail system is located at the approaches.

The deck is supported by five-W900 painted steel girders with steel end and intermediate diaphragms. The ends of each steel girder sit upon elastomeric bearing pads at the abutments. The abutments and wingwalls consist of reinforced, cast-in-place concrete.

2.0 Significant Findings

The guide rail end termination is loose and broken off at the posts at the southeast, southwest and northeast corners of the site.

There are no deck drains at the bridge.

Gravel has accumulated in the expansion joints.

Spalling was observed at the base of the barriers at the barrier joints.

The sealant between the barriers has failed at a few locations.

Spalling with efflorescence was observed at the south exterior face of the deck at the barrier joints.

Three full height medium cracks were observed at the east abutment. Delamination and gravel/disintegrated concrete accumulation was observed at the west abutment.

Severe spalling, delamination, and concrete disintegration was observed along the top of both ballast walls.

One wide crack was observed at the curb and gutter at the southeast corner of the site. Impact

and abrasion damage was observed at the curb and gutters at the southeast and southwest corners of the site.

Several timber spacers are rotated, and a few are broken behind the guide rail at the southwest approach.

The asphalt is worn in front of the base of the concrete barriers.

The asphalt aggregates are exposed on the surface over the entire deck.

Asphalt sealant is missing at the approach slab joints.

Sandbags have remained since 2022 to stabilize the base of the southeast and southwest embankments.

A few of the bearings contain horizontal edge cracks.

Spalling at the concrete curb was observed throughout.

Six timber guide rail posts were observed to have medium rot.

A few of the railing lights flicker.

3.0 Conclusions and Recommendations

The BCI is the ratio of the value of each bridge element in its current state to the total replacement value of the bridge. The overall Bridge Condition Index (BCI) of Duke Street Bridge over Wabigoon River is 73. The BCI value of the bridge indicates the bridge is in good condition.

Although the deck expansion joint seals could not be directly inspected, the severe spalling observed at the top of the ballast walls indicates water has leaked through the seals onto the ballast walls, increasing the rate of deterioration. Therefore, we recommend the expansion joint seals be replaced.

We recommend the following remedial repairs be done within one year:

- Replace termination posts at ends of steel beam guide rails at three corners of the site.
- Replace light bulbs within railing.

We recommend the remaining repairs be done within the next 1-5 years:

- Replace the expansion joints seals, armouring and end dams.
- Replace asphalt and waterproofing system.
- Provide deck drains.
- Remove gravel from the deck joints.

- Repair the spalls at the base of the barriers.
- Replace the sealant at the barrier joints.
- Replace asphalt sealant at the approach slab joints.
- Repair the spalls at the south exterior face of the deck.
- Replace the bearings.
- Inject the cracks at the east abutment with epoxy.
- Repair the delamination and disintegrated concrete areas at the west abutment.
- Repair the spalled, delaminated and disintegrated areas at the ballast walls. Reconstruct the top of the ballast walls.
- Replace damaged sections of curb and gutter.
- Replace and/or re-plumb rotated offset blocks, and tighten loose bolts at the guide rails.
- Replace rotten guide rail posts.

We recommend the next bridge inspection be done in 2026.

4.0 Estimated Construction Costs

The following are the estimated construction costs for the recommended remedial repairs:

Replace guide rail termination posts	\$ 3,000.00
Replace expansion joint assemblies, end dams and seals	\$ 100,000.00
Replace asphalt and waterproofing system	\$ 60,000.00
Provide deck drains	\$ 8,000.00
Remove gravel from deck joints	\$ 500.00
Repair spalls at barriers	\$ 3,500.00
Replace sealant and backer rod at barriers	\$ 2,500.00
Repair spalls at exterior face of deck	\$ 4,500.00
Replace sealant at asphalt approach slab joints	\$ 1,500.00
Replace bearings	\$ 39,000.00
Inject the cracks at the east abutment	\$ 6,500.00
Repair the west abutment delaminated areas	\$ 6,500.00
Repair the ballast walls	\$ 8,000.00
Reconstruct the top of the ballast walls	\$ 16,500.00
Replace/re-plumb offset blocks, tighten loose bolts	\$ 1,000.00
Replace damaged curb and gutter	\$ 3,500.00
Replace rotten guide rail posts	\$ 2,000.00
Subtotal	\$ 266,500.00
Mob/Demob (20%)	\$ 53,500.00
Engineering/Contingency (35%)	\$ 93,000.00
Total Estimated Construction Cost	<u>\$ 413,000.00 + HST</u>

Since there are significant costs required to complete all of the remedial repairs, we recommend the City of Dryden consider having a detailed deck condition survey and feasibility study done by a consultant prior to implementing these repairs. The purpose of this is to assess the condition of the top of the deck, and to review rehabilitation options (i.e. replace expansion joints vs semi-integral abutments, replace barrier walls with new system vs repair, etc.) to determine a feasible

rehabilitation solution.

Even though the structural inspection was carefully done, we do not claim that the observations made represent all of the faults or imperfections which may exist.

P:\2024090 - City of Dryden - Structural Inspection Seven Bridges Two Culverts\Admin\Report\Duke Street Bridge over Wabigoon River\2 - Duke Wabigoon Report.doc

Ontario Structure Inspection Manual – Inspection Form

MTO Site Number:

Inventory Data:			
Structure Name	Duke Street Bridge Over Wabigoon River		
Main Hwy/Road #	Hwy 594	On <input checked="" type="checkbox"/> Under <input type="checkbox"/>	Crossing Type: <input checked="" type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Hwy/Road Name	Highway 594/Duke Street		
Structure Location	2 km west of Hwy 594/Hwy 17 intersection		
Latitude	49° 46' 55" N	Longitude	92° 50' 35" W
Owner(s)	City of Dryden	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Desig. <input type="checkbox"/> Desig./not List <input type="checkbox"/> Desig. & List
MTO Region	Northwestern	Road Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local <input type="checkbox"/>
MTO District	Thunder Bay	Posted Speed	50 No. of Lanes 2
Old County	Rainy River	AADT	% Trucks
Geographic Twp.	544	Inspection Route Sequence	
Structure Type	I-beam or Girders	Interchange Number	
Total Deck Length	24.93 (m)	Interchange Structure Number	
Overall Str. Width	11.0 (m)	Min. Vertical Clearance	(m)
Total Deck Area	274 (sq.m)	Special Routes:	<input type="checkbox"/> Transit <input checked="" type="checkbox"/> Truck <input type="checkbox"/> School <input type="checkbox"/> Bicycle
Roadway Width	10.1 (m)	Detour Length Around Bridge	9 (km)
Skew Angle	0 (Degrees)	Direction of Structure	East / West
No. of Spans	1	Fill on Structure	(m)
Span Lengths	24.65 (m)		

Historical Data:			
Year Built		Year of Last Major Rehab.	2002
Last OSIM Inspection	2022	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	/ / (tonnes)
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey	1997		
Rehab History: (Date/description)			
1997: Structural steel painted.			
2002: Deck replacement and bridge widening/realignment.			

Field Inspection Information:	
Date of Inspection:	October 9, 2024
Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Mohamed Chehabeddine, EIT, JML Engineering
Others in Party:	Lucas Sandberg, JML Engineering
Access Equipment Used:	Boat
Weather:	Sunny
Temperature:	18° C

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Material Condition Survey			
Detailed Deck Condition Survey:	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Non-destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Detailed Timber Investigation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Post-Tensioned Strand Investigation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Underwater Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fatigue Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Seismic Investigation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Structure Evaluation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Monitoring			
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Monitoring Crack Widths:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Investigation Notes: Consider detailed deck condition survey since large rehabilitation scope of work is looming.			

Overall Structure Notes:	
Recommended Work on Structure:	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	Consider a detailed deck condition survey. Replace guide rail end posts. Replace deck joint assemblies. Replace asphalt and waterproofing. Provide deck drains. Repair spalls at south face of deck and barriers. Seal joints between barriers. Remove gravel from joints and replace joint seals. Repair delamination and spalling at abutments and ballast walls. Inject cracks with epoxy at abutments. Replace bearings. Tighten loose guide rail bolts and reset offsets. Replace curb and gutter sections.
Date of Next Inspection:	2026

Suspected Performance Deficiencies

- | | | |
|--|---|---|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |
| Maintenance Needs | | |
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey Bridges - Maintenance | 16 Bridge Deck Drainage |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Decks			Length:	24.93 m	
Element Name:	Wearing Surface			Width:	10.1 m	
Location:	Entire deck			Height:	0.1 m	
Material:	Asphalt			Count:		
Element Type:				Total Quantity:	252 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units <u>m²</u> / m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Several patched potholes at east end. Drainage toward south side. No deck drains on bridge. Asphalt surface abrasion over most of deck.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Provide deck drains. Replacing asphalt and waterproofing as part of future rehabilitation project.						

Element Group:	Decks			Length:	24.93 m	
Element Name:	Deck Top			Width:	11 m	
Location:	Entire deck			Height:	0.225 m	
Material:	Cast-in-place concrete			Count:		
Element Type:	Cast-in -place conc on supports			Total Quantity:	274 sq m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input checked="" type="checkbox"/>		
Protection System:	Asphalt					Perform. Deficiencies
Condition Data:	Units <u>m²</u> / m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Unable to inspect deck top due to wearing surface.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Decks			Length:	2 m	
Element Name:	Soffit – Thin Slab			Width:	11.4 m	
Location:	End			Height:		
Material:	Cast-in-place concrete			Count:	2 ends	
Element Type:				Total Quantity:	46 sq m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units <u>m²</u> / m / each / % / all	Exc.	Good	Fair	Poor	
Comments:						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Decks			Length:	20.93 m	
Element Name:	Soffit – Thin Slab			Width:	1 m	
Location:	Exterior			Height:		
Material:	Cast-in-place concrete			Count:		
Element Type:				Total Quantity:	21 sq m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Hairline cracks were observed. Spalling and efflorescence at south exterior face at barrier joints.						
Recommended Work:				Maintenance Needs:		
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Repair spalls.						

Element Group:	Decks			Length:	20.93 m	
Element Name:	Soffit – Thin Slab			Width:	10.4 m	
Location:	Interior			Height:		
Material:	Cast-in-place concrete			Count:		
Element Type:				Total Quantity:	218 sq m	
Environment:	<u>Benign</u> / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: (Empty)						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
				00		

Element Group:	Joints			Length:	11.0 m	
Element Name:	Seals/Sealants			Width:		
Location:	East and West joints			Height:		
Material:	Other			Count:	1 per joint	
Element Type:	Compression seal			Total Quantity:	22 m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input checked="" type="checkbox"/>		
Protection System:	Other					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Granular material has accumulated in the joints. Spalling at the ballast walls suggest the seals may have failed.						
Recommended Work:				Maintenance Needs:		
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Replace joint seals.				Remove granular material.		

Element Group:	Joints				Length:	10.1 m
Element Name:	Concrete End Dams				Width:	0.3 m
Location:	East and West joints				Height:	
Material:	Cast-in-place concrete				Count:	2 per joint
Element Type:					Total Quantity:	12 sq m
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:	None					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m²/m / each / % / all			12		00
Comments: Concrete surface contains abrasion damage with loss of cement and exposed aggregate at surface.						
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs: 00	
				<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
Replace or repair concrete end dams.						

Element Group:	Joints				Length:	10.1 m
Element Name:	Armouring/Retaining Devices				Width:	
Location:	East and West joints				Height:	
Material:	Steel				Count:	2 per joint
Element Type:					Total Quantity:	40 m
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m²/m / each / % / all			40		00
Comments: West joint damaged by snow plow. Armouring is effective, but aged and corroding.						
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs: 00	
				<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
Replace deck joint assemblies.						

Element Group:	Barriers				Length:	40.65 m
Element Name:	Barrier/Parapet Walls Interior Face				Width:	0.275 m
Location:	North and south sides				Height:	0.80 m
Material:	Precast concrete				Count:	2
Element Type:	Parapet Wall with two rails				Total Quantity:	87 sq m
Environment:	Benign / Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:	None					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m²/m / each / % / all		83	2	2	16
Comments: Spalling has occurred at the base of the interior barrier wall at all of the barrier joints. Several seals at the barrier joints have gaps.						
Recommended Work:				<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs:	
				<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
Repair spalled concrete and seal joints.						

Element Group:	Barriers			Length:	40.65 m	
Element Name:	Barrier/Parapet Walls Exterior Face			Width:	0.275 m	
Location:	North and south sides			Height:	0.80 m	
Material:	Precast concrete			Count:	2	
Element Type:	Parapet Wall with two rails			Total Quantity:	65 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Efflorescence observed at the exterior of the bridge deck where damaged joint seals are located. Spalls observed at barrier joints. Water is leaking out from the base of the barrier wall to the exterior face of the bridge soffit.						
Recommended Work:				Maintenance Needs:		00
<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Repair spalls.						

Element Group:	Barriers			Length:	40.65 m	
Element Name:	Railing Systems			Width:		
Location:	North and South side			Height:	0.53 m	
Material:	Steel			Count:	2 per side	
Element Type:	2 Rail Metal Railing - Steel			Total Quantity:	163 m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Two - 90 mm diameter horizontal rails per side, panel lengths vary.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Barriers			Length:	0.09 m diameter	
Element Name:	Posts			Width:	0.09 m	
Location:	North and south side			Height:	0.53 m	
Material:	Steel			Count:	10 each side	
Element Type:				Total Quantity:	20	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² /m / <u>each</u> / % / all	Exc.	Good	Fair	Poor	
Comments:						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's			Length:	2.0 m	
Element Name:	Girders			Width:	0.3 m	
Location:	End			Height:	0.9 m	
Material:	Steel			Count:	10	
Element Type:	I-Type			Total Quantity:	27 sq m	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units m ² /m / each / % / all	Exc.	Good	Fair	Poor	
Comments: Light corrosion at top flange tip at south face of exterior girder.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's			Length:	20.65 m	
Element Name:	Girders			Width:	0.3 m	
Location:	Middle			Height:	0.9 m	
Material:	Steel			Count:	5	
Element Type:	I-Type			Total Quantity:	279 sq m	
Environment:	<u>Benign</u> / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units m ² /m / <u>each</u> / % / all	Exc.	Good	Fair	Poor	
Comments: Light corrosion at top flange tip at south face of exterior girder.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's			Length:	2.4 m	
Element Name:	Diaphragms			Width:		
Location:	End			Height:		
Material:	Steel			Count:	4 per end	
Element Type:	Channels			Total Quantity:	8	
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units m ² /m / <u>each</u> / % / all	Exc.	Good	Fair	Poor	
Comments:						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Beams/MLE's			Length:	2.4 m	
Element Name:	Diaphragms			Width:		
Location:	Intermediate			Height:		
Material:	Steel			Count:	4 per bay	
Element Type:	Channels			Total Quantity:	12	
Environment:	Benign Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc. 4	Good 8	Fair	Poor	
Comments:						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Coatings			Length:		
Element Name:	Structural Steel			Width:		
Location:	End			Height:		
Material:	Steel			Count:		
Element Type:				Total Quantity:	306 sq m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good 304	Fair 1	Poor 1	
Comments:						
Light corrosion at top flange tip of south girder.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Coatings			Length:		
Element Name:	Railing Systems/Hand Railings			Width:		
Location:	North and South barriers			Height:		
Material:	Steel			Count:		
Element Type:				Total Quantity:	87.0 m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good 87	Fair	Poor	
Comments:						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Abutments			Length:		
Element Name:	Abutment Walls			Width:	11.0 m	
Location:	East and west abutments			Height:	2.4 m	
Material:	Cast-in-place concrete			Count:	2	
Element Type:	Gravity wall			Total Quantity:	53 sq m	
Environment:	<u>Benign</u> Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	<u>m²</u> / m / each / % / all		34	13	6	00
Comments: 6.0 sq m of delamination and gravel/disintegrated concrete accumulation at west abutment. Three full height medium cracks at east abutment.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs:		02
			<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Repair delaminated concrete. Inject cracks with epoxy.			Remove gravel.			

Element Group:	Abutments			Length:		
Element Name:	Ballast Walls			Width:	11.0 m	
Location:	East and west abutments			Height:	2.0 m	
Material:	Cast-in-place concrete			Count:	2	
Element Type:				Total Quantity:	44.0 sq m	
Environment:	Benign / Moderate / <u>Severe</u>			Limited Inspection <input type="checkbox"/>		
Protection System:	None					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	<u>m²</u> / m / each / % / all		20	12	12	00
Comments: Severe spalling/concrete disintegration along top of both ballast walls and at south corner of west wall. Delamination at both walls.						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs:		00
			<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Repair concrete.						

Element Group:	Abutments			Length:	4.0 m	
Element Name:	Wingwalls			Width:		
Location:	Four corners of bridge			Height:	2.0 m	
Material:	Cast-in-place concrete			Count:	4	
Element Type:	Reinforced concrete			Total Quantity:	32.0 sq m	
Environment:	Benign / Moderate / Severe			Limited Inspection <input type="checkbox"/>		
Protection System:						Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	<u>m²</u> / m / each / % / all		32			00
Comments:						
Recommended Work:			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs:		00
			<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Abutments			Length:	
Element Name:	Bearings			Width:	
Location:	East and West abutment			Height:	
Material:	Other			Count:	5 each end
Element Type:	Elastomeric pad			Total Quantity:	10
Environment:	Benign / <u>Moderate</u> / Severe			Limited Inspection <input type="checkbox"/>	
Protection System:					Perform. Deficiencies
Condition Data:	Units m ² / m / <u>each</u> / % / all	Exc.	Good	Fair	Poor
				10	
Comments: Bearings are cracked.					
Recommended Work:			<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace	Maintenance Needs: 00	
			<input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
Replace bearings..					

Element Group:	Foundations			Length:	
Element Name:	Foundation (below ground level)			Width:	
Location:				Height:	
Material:				Count:	
Element Type:				Total Quantity:	
Environment:	<u>Benign</u> / Moderate / Severe			Limited Inspection <input type="checkbox"/>	
Protection System:					Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / all	Exc.	Good	Fair	Poor
		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments: Foundation appears to be stable.					
Recommended Work:			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs: 00	
			<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Element Group:	Embankments & Streams			Length:	
Element Name:	Streams & Waterways			Width:	24.6 m at upstream face
Location:				Height:	
Material:				Count:	
Element Type:				Total Quantity:	
Environment:	<u>Benign</u> / Moderate / Severe			Limited Inspection <input type="checkbox"/>	
Protection System:					Perform. Deficiencies
Condition Data:	Units m ² / m / each / % / <u>all</u>	Exc.	Good	Fair	Poor
		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Comments: Stream occupies full length of structure between abutments and is unobstructed. Water level was 2.3 m below top of deck at time of inspection. A floating boom is located upstream. A controlled dam structure is located downstream.					
Recommended Work:			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace	Maintenance Needs: 00	
			<input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	

Element Group:	Embankments & Streams				Length:	
Element Name:	Embankments				Width:	
Location:	East and West embankments				Height:	
Material:	Gravel				Count:	
Element Type:	Vegetation				Total Quantity:	
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m ² / m / each / % / <u>all</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	00
Comments: Embankments appear to be stable, covered in vegetation.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Embankments & Streams				Length:	
Element Name:	Slope Protection				Width:	
Location:	East and West embankments				Height:	
Material:	Other				Count:	
Element Type:	Vegetation				Total Quantity:	
Environment:	<u>Benign</u> Moderate / Severe				Limited Inspection <input type="checkbox"/>	
Protection System:						Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	m ² / m / each / % / <u>all</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	00
Comments: Stable vegetation growth at each embankment. In 2022 sandbags had been placed at southeast and southwest corners to protect against recent floods.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:	Approaches				Length:	4.0 m
Element Name:	Wearing Surfaces				Width:	10.1 m
Location:	East and west approaches				Height:	0.1 m
Material:	Asphalt				Count:	2
Element Type:					Total Quantity:	80.2 sq m
Environment:	Benign / Moderate <u>Severe</u>				Limited Inspection <input type="checkbox"/>	
Protection System:	None					Perform. Deficiencies
Condition	Units	Exc.	Good	Fair	Poor	
Data:	<u>m²</u> / m / each / % / all		77	3		00
Comments: 2 patched potholes at west approach, 3 at east approach. Asphalt appears worn due to abrasion and age of pavement.						
Recommended Work:				Maintenance Needs:		00
<input type="checkbox"/> Rehab <input checked="" type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Replace asphalt.						

Element Group:	Approaches			Length:	
Element Name:	Curb/Gutters			Width:	
Location:	East and West approaches			Height:	
Material:	Cast-in-place concrete			Count:	6.0 m per corner
Element Type:				Total Quantity:	24.0 m
Environment:	Benign / Moderate Severe			Limited Inspection <input type="checkbox"/>	
Protection System:	None				Perform. Deficiencies
Condition Data:	Units m ² (m) / each / % / all	Exc.	Good	Fair	
<p>Comments: Wide crack, impact and abrasion damage at base at southeast and southwest corners of the site.</p>					
Recommended Work:			<input type="checkbox"/> Rehab <input type="checkbox"/> Replace <input type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	Maintenance Needs:	18
				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	
				Repair damaged sections.	

Element Group:	Approaches			Length:	62.1 m W, 81.5 m E sides	
Element Name:	Railing Systems			Width:		
Location:	East and West approaches			Height:	0.53 m	
Material:	Steel			Count:		
Element Type:	Steel Flex on wood post			Total Quantity:	144 m	
Environment:	Benign / Moderate Severe			Limited Inspection <input type="checkbox"/>		
Protection System:	Hot dip galvanizing					Perform. Deficiencies
Condition Data:	Units m ² (m) / each / % / all	Exc.	Good	Fair	Poor	
<p>Comments: Guide rail end termination broken off at last post at three corners. Some offset timbers rotated and others are rotten.</p>						
Recommended Work:			<input checked="" type="checkbox"/> Rehab <input type="checkbox"/> Replace <input checked="" type="checkbox"/> 1-5 years <input type="checkbox"/> 6-10 years	Maintenance Needs:	18	
				<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 year <input type="checkbox"/> 2 year		
Provide new posts at end termination of guide rail at 3 corners of site.				Tighten loose bolts. Provide new, and realign other offset timbers.		



Photo 1: East approach to bridge.



Photo 2: West approach to bridge.



Photo 3: Upstream elevation looking north.



Photo 4: Downstream elevation looking south.




Photo 5: Deck cross-section.



Photo 6: Underside of bridge.



Photo 7: East abutment.



Photo 8: West abutment.



Photo 9: Downstream view from bridge.



Photo 10: Upstream view from bridge.



Photo 11: East expansion joint.



Photo 12: West expansion joint.



Photo 13: Northeast embankment.



Photo 14: Northwest embankment.



Photo 15: Southeast embankment.



Photo 16: Southwest embankment.



Photo 17: Broken end post (typ. 3 locations).



Photo 18: Deteriorated concrete at end dams, corroded armoring, broken expansion joint, and gravel accumulation above seal at expansion joint (typ.).



Photo 19: Abrasion damage to asphalt on deck.



Photo 20: Abrasion damage to barriers and asphalt along side of deck (typ.).



Photo 21: Spalled concrete and missing sealant at barrier joint (typ.).



Photo 22: Poor sealant and asphalt along east approach slab joint (typ.).



Photo 23: Spall at south face of deck.



Photo 24: Bearing with horizontal cracks (typ.).



Photo 25: Narrow vertical crack at east abutment.



Photo 26: Delaminated concrete at west abutment.



Photo 27: Spalled ballast wall at southwest corner of bridge (typ.).



Photo 28: Abrasion damage to curb and gutter at southwest corner of site.



Photo 29: Sandbags at base of southeast embankment.